
Change Sheet

Bulletin 7012-00E Ed : 03/b

Errors contained in this catalog have to be corrected as follows.

Notes

- Page 3 Icon
Error "Voice Memo" icon is available for the DL750 and DL750P
Correct Remove "Voice Memo" icon from the DL750 and DL750P
- Page 11 DL750/DL750P/SL1400 Selection
Error Acquisition → Voice memo: available for DL750 and DL750P
Correct Acquisition → Voice memo: Not available for DL750 and DL750P
- Page 12 Main Specifications (Main Unit)
Error Specificatiopns for Voice Memo and Voice Comment: available for DL750 and DL750P
Correct Specificatiopns for Voice Memo and Voice Comment: Not available for DL750 and DL750P
- Page 14 Main Specifications (Main Unit)
Error *6: with the /C10 option
Correct *6: Standard
- Page 19 Complete Connectivity
Error Voice memo input/output (DL750/DL750P): available
Correct Voice memo input/output (DL750/DL750P): Not available

Error Ethernet (optional)
Correct Ethernet (Standard)
- Page 20 DL750/DL750P ScopeCorder Model Numbers and Suffi x Codes
Error Others: /C10 Ethernet interface
Correct Others: /C10 Ethernet interface (Standard)